

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L5	933	399/120 358-360	US-PGPUB; USPAT	OR	ON	2006/02/04 18:10
L6	0	399/120,358-360	US-PGPUB; USPAT	OR	ON	2006/02/04 18:10
L7	624	399/120,358-360.ccls.	US-PGPUB; USPAT	OR	ON	2006/02/04 18:50
L14	1	399/120,358-360.ccls. and (patch band) same (recycl\$3)	US-PGPUB; USPAT	OR	ON	2006/02/04 18:12
L15	35	399/120,358-360.ccls. and (patch band)	US-PGPUB; USPAT	OR	ON	2006/02/04 18:12
L16	2	("399"/\$.ccls. g03g\$.ipc.) and recyc\$3 same (percent ration) same (test\$4 patch band)	US-PGPUB; USPAT	OR	ON	2006/02/04 18:15
L17	27	("399"/\$.ccls. g03g\$.ipc.) and recyc\$3 same (percent ratio) same (detect\$4 test\$4 patch band)	US-PGPUB; USPAT	OR	ON	2006/02/04 18:30
L18	14	("399"/\$.ccls. g03g\$.ipc.) and recyc\$3 same (percent ratio) same (detect\$4 test\$4 patch band)	EPO; JPO; DERWENT	OR	ON	2006/02/04 18:31
L19	17	((toner developer) and recyc\$4 and (band patch test\$3 detect\$4)).clm.	US-PGPUB	OR	ON	2006/02/04 18:51
L20	69176	((toner developer) and recyc\$4 and (band patch test\$3 detect\$4) sensor).clm.	US-PGPUB	OR	ON	2006/02/04 18:51
L21	4	((toner developer) and recyc\$4 and (band patch test\$3 detect\$4) and sensor).clm.	US-PGPUB	OR	ON	2006/02/04 18:51
L22	19	((toner developer) and recyc\$4 and (band patch test\$3 detect\$4 sensor)).clm.	US-PGPUB	OR	ON	2006/02/04 18:52
L23	1731	((toner developer) and (band patch test\$3 detect\$4 sensor)).clm.	US-PGPUB	OR	ON	2006/02/04 18:52
L24	222	((toner developer) and (band patch)).clm.	US-PGPUB	OR	ON	2006/02/04 18:52
L25	1	399/120,358-360.ccls. and ((toner developer) and (band patch)).clm.	US-PGPUB	OR	ON	2006/02/04 18:52